

TECHNICAL SERVICE BULLETIN

BULLETIN NUMBER:
SB92-04-001

ISSUE DATE
March 28, 1992

GROUP
ELECTRICAL

BY SERVICE MAN FOR:	SERVICE MANAGER ✓	TECHNICIAN ✓	SERVICE ADVISOR ✓	PARTS DEPT	WARRANTY PERSONNEL
------------------------	----------------------	--------------	----------------------	---------------	-----------------------

RODEO (UC) ELECTRICAL WIRING DIAGRAMS (WORKSHOP MANUAL CORRECTIONS)

AFFECTED VEHICLES

1991-92 Rodeo (UC) models equipped with V6 engine.

SERVICE INFORMATION

Wiring diagrams containing ECM relay, starter circuit, A/T shift lock circuit and license plate lamp connector are incorrectly shown in the following Workshop Manuals:

Manual	Page
1991/92 Rodeo (UC) Workshop Manual (Publication No. AIMI-SVC-222, part Number 2-90992-072-0)	8-42, 8-44, 8-48, 8-54, 8-55, 8-68, 8-84, 8-85, 8-142, 8-143, 8-144, 8-198
1991 Rodeo (UC) Workshop Manual (Publication No. AIMI-SVC-195, part Number 2-90991-072-0)	8-40, 8-42, 8-46, 8-48, 8-52, 8-53, 8-82, 8-83, 8-140, 8-141, 8-142

This Service Bulletin contains the following corrected Workshop Manual pages ('91/92 WSM pages referenced):

- Page 8-42: ECM relay connector pin numbers and ECM relay diode are corrected.
- Page 8-44 and 8-68: ECM relay connector pinout view corrected.
- Page 8-48: ECM relay connector pin numbers are corrected. Clutch start switch (M/T) and starter relay connection to the starter switch are added.
- Pages 8-54, 8-55, 8-84, 8-85, 8-142 thru 8-144: License plate lamp connector corrected.
- Page 8-198 ('92 models only): Circuit for the heater relay and alternator is added.

NATIONAL SERVICE DEPARTMENT

